MATERIAL SAFETY DATA SHEET

EXT FLAT HOUSE PAINT - TINT BASE 1610-01

PRODUCT NAME: EXT FLAT HOUSE PAINT - TINT BASE

HMIS CODES: H F R P

1*0 0 B

Page:

1

MANUFACTURER'S NAME

P TUCT CODE: 1610-01

: Conco Paint Company

ADDRESS

: 12234 Los Nictos Road, Sante Fe Springs, CA 90670

EMERGENCY PHONE

: (800) 486-7889

SUPERSEDES DATE : 3/23/98

INFORMATION PHONE DATE PRINTED

: (800) 486-7889

REVISION DATE : 5/12/99

: 5/29/99

SECTION II - HAZARDOUS INGREDIENTS/SARA III INFORMATION

REPORTABLE COMPORTER'S	CAS HUMBER	VAPOR PRESSURE nm Eg & TEMP		WEIGHT PERCENT	
* ETHYLENE GLYCOL ACGIE TLV: 50PPN	107-21-1	.06	77 F	2.1	
*# TETRACELOROTSOPETHALORITRILE (CELOROTHALORIL) NONE ESTABLISHED	1897 - 45-6	N/A	N/A	0 28	

SECTION III - PHYSICAL/CHEMICAL CHARACTERISTICS ----

* Indicates toxic chemical(s) subject to the reporting requirements of section 313 of Title III and of 40 CFR 372. # Indicates toxic chemical(s) subject to the reporting requirements of California Proposition 65 Safe Drinking Water and Toxic

Emforcement Act.

BOILING RANGE: 387 F

SPECIFIC GRAVITY (H2O=1): 1.32 EVAPORATION RATE: Slower than ether.

VAPOR DENSITY: Lighter than air. COATING V.O.C.: 145 g/l SOLUBILITY IN WATER: Complete.

MATERIAL V.O.C.: 45 g/l

APPEARANCE AND ODOR: Typical for water based paints.

SECTION IV - FIRE AND EXPLOSION HAZARD DATA

FLASH POINT: 241 F METHOD USED: TCC FLANNABLE LIMITS IN AIR BY VOLUME- LOWER: 3.2 UPPER: 15.3

EXTINGUISHING MEDIA: Foam, CO2, Dry Chemical, or Water Fog.

SPECIAL FIREFIGHTING PROCEDURES

Cool containers with water spray.

UNUSUAL FIRE AND EXPLOSION HAZARDS

Closed container exposed to high temperatures may explode or burst due to build up of steam pressure.

SECTION V - REACTIVITY DATA ---

STABILITY: Stable. CONDITIONS TO AVOID

INCOMPATIBILITY (MATERIALS TO AVOID)

Avoid contact with strong exidizing agents.

MATERIAL SAFETY DATA SHEET

1610-01

EXT FLAT HOUSE PAINT - TINT BASE

Page:

2

ARDOUS DECOMPOSITION OR BYPRODUCTS

May form toxic materials: Carbon Dioxide, Carbon Monoxide, Various Bydrocarbons, etc. on thermal decomposition.

HAZARDOUS POLYMERIZATION: Will not occur.

SECTION VI - HEALTH HAZARD DATA

INHALATION HEALTH RISKS AND SYMPTOMS OF EXPOSURE

Adverse bealth effects from vapors or spray mists in poorly ventilated areas may include irritation of the mucous membranes of the nose, throat, and respiratory tract and symptoms of headache and nausea.

SKIN AND EYE CONTACT HEALTH RISKS AND SYMPTOMS OF EXPOSURE

EYES: In direct contact, may cause irritation. SKIW: Prolonged and repeated contact with product may cause skin irritation.

SKIN ABSORPTION HEALTH RISKS AND SYMPTOMS OF EXPOSURE

Redness, drying of the skin, or other signs of irritation or contact dermititis.

INGESTION HEALTH RISKS AND SYMPTOMS OF EXPOSURE

Can cause gastrointestinal irritation, nausea, voniting, and diarrhea.

HEALTH HAZARDS (ACUTE AND CHRONIC)

ACUTE: Hay cause irritation to skin and eyes, quastrointestinal irritation, nausea, and voniting. CHRONIC: Prolonged or repeated exposured above TLV may result in permanent brain and nervous system damage.

CARCINOGENICITY: NTP CARCINOGEN: No IARC MONOGRAPHS: Yes OSHA REGULATED: No W' "WG! This product contains chemical(s) known to the State of California to cause cancer. (California Health and Safety Code Se. .on 25249.5) (Prop. 65). WARNING! This product contains chemical(s) known to the State of California to cause birth defects or other reproductive harm. (California Health and Safety Code Section 25249.5) (Prop. 65).

MEDICAL CONDITIONS GENERALLY AGGRAVATED BY EXPOSURE

May be adoravating to some skin and respiratory conditions, and to pre-existing liver and/or kidney disorders.

EMERGENCY AND FIRST AID PROCEDURES

EYES: Flush with large amounts of water for at least 15 minutes. Take to a physician.

SKIN: Wash affected areas with scap and water. Remove contaminated clothing. If irritation persists, consult physician.

IMELIATION: Remove to fresh air. Treat symptomatically. Consult physician.
IMERSTION: Drink 1 or 2 glasses of water to dilute. DO NOT INDUCE WOMITING. CONSULT A PHYSICIAN OR POISON CONTROL CENTER IMMEDIATELY. TREAT SYMPTOMATICALLY.

SECTION VII - PRECAUTIONS FOR SAFE HANDLING AND USE

STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED

Dike, contain, or absorb with inert materials. Transfer to containers for recovery or disposal. Prevent runoff into severs, streams, or other hodies of water.

WASTE DISPOSAL METHOD

Dispose of in accordance with all local, state and federal regulations.

PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING

Do not expose to extremes in temperature. Avoid exposure to high temperatures. DO NOT ALLOW TO FREEZE.

ER PRECAUTIONS

DO #OF TAKE INTERNALLY. Avoid prolonged or repeated exposure to levels above TLV. KEEP OUT OF REACH OF CHILDREN.

MATERIAL SAFETY DATA SHERT EXT FLAT HOUSE PAINT - TINT BASE

1610-01

Page:

F PIRATORY PROTECTION

Not normally required. If TLV is exceeded, use WIOSH/MSSHA approved organic vapor and mist, supplied air, or self-contained breathing apparatus. Avoid breathing sanding dust.

VENTILATION

Ose adequate mechanical (general and/or local) ventilation to maintain exposure below TLV.

PROTECTIVE GLOVES

Wear resistant gloves such as polyethylene.

EYE PROTECTION

Use chemical splash goggles or OSHA permitted safety glasses.

OTHER PROTECTIVE CLOTHING OR EQUIPMENT

Wear impervious clothing. Eyewash station.

WORK/HYGIENIC PRACTICES

Wash hands before eating or using restrooms. Remove and wash all contaminated clothing before reuse.

SECTION IX - DISCLAIMER

The information contained herein is furnished without warranty of any kind. Employers should use this information only as a supplement to other information gathered by them and must make independent determination of suitability and completeness of information from all sources to assure proper use of these materials and the safety and health of employees.